

Stecker Stepper-Platine Platz 3

1a	Gnd		1c	Gnd	
2a	Gnd		2c	Gnd	
3a	X- Enable	D 43	3c	Y-Enable	D 42
4a	Mode 1	D 39	4c	Mode 2	D 38
5a	X-Step Clock	D 37	5c	Y Step	D 36
6a	X-Step direction	D 35	6c	Y-Step direction	D 34
7a	Ref X	AD 14	7c	Ref Y	A 15
8a			8c		
9a			9c		
10a			10c		
11a			11c		
12a			12c		
13a			13c		
14a			14c		
15a			15c		
16a			16c		
17a			17c		
18a			18c		
19a			19c		
20a			20c		
21a			21c		
22a			22c		
23a			23c		
24a			24c		
25a			25c		
26a			26c		
27a			27c		
28a	220V ~		28c	220V ~	
29a	220V ~		29c	220V ~	
30a			30c		
31a	220V ~		31c	220V ~	
32a	220V ~		32c	220V ~	

SubD Stecker femal 15 pol.

1	Motor X Phase B-	9	Motor X Phase A-
2	Motor X Phase B+	10	Motor X Phase A+
3	Motor Y Phase B-	11	Motor Y Phase A-
4	Motor Y Phase B+	12	Motor Y Phase A' +
5		13	
6		14	
7	Ref Y, TTL	15	Gnd
8	Ref. X TTL		

Scanner Kabel

15pol	25pol		
1	14	gelb	Motor X Phase B-
2	15	Grün	Motor X Phase B+
3	1	Gelb/weiß	Motor Y Phase B-
4	2	Grün/weiß	Motor Y Phase B+
5	6	Braun/weiß	
6	5	Grau/Weiß	
7	8	Violett	Ref Y, TTL
8	20	Schwarz	Ref X, TTL
9	16	Rot	Motor X Phase A-
10	17	blau	Motor X Phase A+
11	3	Rot/weiß	Motor Y Phase A-
12	4	Blau/weiß	Motor Y Phase A´+
13	19	Weiß	
14	18	Grau	
15	8,9,21,22	Braun	Gnd

